
## NEWTON CROUCH

## STANDARD SPINNER MOTORS, 1" SHAFT



	Ref	Qty 1½"	Part No.	Description
	Α	1	HM-J0592	Cover, End, Port
	В	2	HM-A1014	Gasket
	С	4	HM-J1032	Bearing, Gear
	D	2	HM-J1058	Thrust Plate
	Е	1	HM-I05771533	Center Section, 11/2" w/ O-Ring
	F	1	HM-E1006M15	Gear Set, 11/2" Center
	G	1	HM-K0574NC	Cover, Shaft End
$\vee$	Н	2	HM-R300655*	O-Ring
$\otimes$	1	1	HM-X73371	Oil Seal
$\vee$	J	1	HM-EA1669	Bearing, Spacer **

	Ref	Qty 1½"	Part No.	Description
	K	1	UJ-8000	Grease Fitting
	L	1	HM-X1020	Gear, Key
	М	1	HM-X1013	Shaft Key
	Ν	1	HM-M113513	Shaft
	0	2	HM-X6940	Bearing, Shaft
•	Р	1	NC-015092BG	Motor Cap w/ Seal
	P1	1	GB-300004	Seal, Motor Cap
	Q	3	BN-SSFH1478	Screw, Flat Head, 1/4" x 2", 20UNC
	R	10	BN-HH12414	Screw, Hex Head, ½" x 4 ¼", 13UNC
	$\checkmark$	1	NC-8080KIT	Double Bearing Repair Kit, Includes all≪

<sup>\*\*\*</sup> Ref O - Special installation. See note on drawing.





<sup>\* 2</sup> slots to put O-Ring: on in top & bottom slot only

<sup>\*\*</sup> Bearing Spacer is concave. Install concave side up.